



(Compatible with original centre stand.
 In case there is one, it is necessary to
 replace the original rubber fit on the centre stand
 and replace it with the rubber cod.206267,
 the nut 200298 and the spacer 206366)



Spring and rubber
 replacement kit
 Cod.303949001R



WARNING

-it is advisable to optimize the carburation by remapping
 the stock ECU or by adopting an additional ECU unit.

ART. 80011 SPARE PARTS

DUCATI MULTISTRADA 950/950S
 (compatible with original under cowl)

(A) FITTING KIT cod. 3080011601R